

Traffic Crash Report

Date/Time and Location

CARD Event #:	P038434588	DOCLOC #:	
Occurrence ID #:		Occurred Date/Time:	20/07/2019 12:05
Location Description:	NORTHERN MOTORWAY, FREEMANS BAY, AUCKLAND		
Location Type:	Point Of Impact	Side Road or Feature:	
GPS Coordinates:	-36.849648, 174.753235		
Reported By:	WLW816		

What Happened

Officer Notes:	<p>██████ was driving a white Ferrari motor vehicle, registration number ██████ heading north on Northern Motorway, Freeman's Bay, Auckland.</p> <p>He was in lane 1 after getting onto motorway from Wellington Street on Ramp.</p> <p>All of sudden, the car started to swerve prior Victoria Tunnel.</p> <p>██████ managed to keep the car as close as to the left lane to avoid the other traffic.</p> <p>As a result, he hit the left barrier a few time time before coming to a stop in lane 2.</p> <p>████████████████████ reviewed by section supervisor and senior staff. After reviewing CCTV it appears the vehicle was travelling slightly faster than other cars in the immediate area and has lost control while in a straight line indicating that the driver Has done a sudden increase of speed or manoeuver while revving the vehicles engine causing it to lose control.</p>
Objects Hit:	Car vs Barrier
Crash Diagram:	See final page of this report.

Why Crash Happened

Road & Roadside Factors:	The road surface was wet. There was no obstruction on the road.
Road User Factors:	██████ holds a current UK driver's licence and his last arrival NZ date is 21/03/19.
Vehicle Factors:	Vehicle holds current registration but WOF is expired on 12/07/19. The car has not been driven for a long time. It is unknown whether the crash was caused by any faulty of the vehicle.
Speed Factors:	There are no evidence of excessive speed was a factor.
Environmental Factors:	The road surface was wet. There was no obstruction on the road. Traffic was busy at the time.

Vehicles Involved

Vehicle: 2013 Ferrari 458, Sports Car, Car White

Vehicle Type:	Car	CAS Vehicle Type:	Car/Wagon
Primary Colour:	WHITE	Secondary Colour:	N/A
WoF/CoF Expiry:	12/07/2019	TSL:	N/A
Additional Devices:		Total Passengers (Front):	1
Total Passengers (Rear)	0	Total Passengers (Other):	0
Vehicle Usage:	Private		

SPEED AND TRAVEL DIRECTION

Road Travelled On:	Northern Motorway	Travel Direction:	North
State Before Crash:	Moving forward	Suspected Speed Before Crash:	60 kmh
Too Fast for Conditions?	No		

DAMAGE SEVERITY AND LOCATION

Damage Severity:	<ul style="list-style-type: none">• Extensive	Specific Damage Location:	<ul style="list-style-type: none">• Front - 1• Right - 3• Right - 2• Right - 1• Left - 4• Front - 6
------------------	---	---------------------------	--

DRIVER DETAILS

Gender:	Unknown	Occupation:	
Address:			
Phone Number:			
Ethnicity:	Ethnicity Description:		
Driver's Comments:	<p>I was doing a test drive of a Ferrari motor vehicle, registration number</p> <p>I was heading north in lane 1 on Northern Motorway. Before the Victoria tunnel, the car slipped and I tried hard to control it and kept as close as to the left side of the road to avoid the traffic.</p> <p>It hit the barrier a few times before coming to a stop in lane 2.</p>		
INJURIES			
Injury Scale:	None		
Restraint Used:	Yes	Supplementary Devices:	• Airbag Deploy
LICENCE DETAILS			
NZ Licence #:		Licence Conditions Met?:	Yes
Licence Type:	Full	Licence Status:	Current
JOURNEY INFORMATION			
Came From:	Epsom	Day Start Time:	07:00
Company Vehicle?	Yes		
Journey Part of Work?	No	Journey Purpose:	Personal Travel eg: Shopping, sports, visiting friends
IMPAIRMENT			
Passive Breath Test:	Negative	Breath Screening Test:	Not Done
Evidential Breath Test:		Breath Reading:	
Drugs Involved:	Not Suspected		
Blood Tested:	Not Done		

PASSENGER DETAILS (1)

Passenger's Comments:	I don't remember much about the crash. I was on my phone before the crash. All of sudden, our car started to swerve and hit the barrier a few times.		
INJURIES			
Injury Scale:	None		
Restraint Used:	Yes	Supplementary Devices:	
LICENCE DETAILS			
NZ Licence #:			
Licence Type:	Full	Licence Status:	Current
SEATING AND SAFETY			
Passenger Seat Location Row:	Front Row	Seat:	Left

Other Vehicles Involved

There are no Other Vehicles Involved (e.g. Cycles) on this Traffic Crash Report.

Pedestrians

There are no Pedestrians on this Traffic Crash Report.

Witnesses

There are no Witnesses on this Traffic Crash Report.

Environment and Road Conditions

Speed Limit:	80	Temporary Speed Limit:	
Road Curvature:	Curved	Speed Advisory:	None
Road Type:	1-Way		
Total Lanes:	3	Road Feature:	Tunnel
Gradient:	Flat Road	Surface Type:	Sealed
Surface Moisture:	Wet	Surface Condition(s):	
Special Purpose Lane:		Road Markings:	• None
Precipitation:	Fine	Weather:	
Barriers:	<ul style="list-style-type: none">• Right Side - Rigid/Concrete• Left Side - Rigid/Concrete		
Natural Light:	Bright Sun	Street Light:	Off
Crash Relates to Intersection?	No	Junction:	None

Outcome

Enforcement Details: [REDACTED]

Crash Diagram



Date Uploaded: 15/08/2019 01:02

Workflow History

Date/Time	User ID	Status	Comments
19/08/2019 06:35:51	JABC01	Accepted	
15/08/2019 01:02:10	WLW816	Submitted	
20/07/2019 12:34:00	TSED20	Incomplete	